

Modify section 25 90 00 GUIDE SEQUENCE OF OPERATION per the following. Remainder of section is unchanged.

Delete the linked document "Enterprise Utility Management System (EUMS) Equipment Control Strategies (dated June 2011 in its entirety, and replace with new link to new document (dated January 2012) attached to this ticket. Revise the link to match new document named.

End of Revision

Update Commentary:

Section was updated primarily for the following reasons:

- 1) Correct the number of space type classifications from 4 to 5.